

## Vehicle Inspection form

| OSCE – Plate               | Type                     | Model                  |
|----------------------------|--------------------------|------------------------|
| OSCE 040 PA                | Mitsubishi               | Pajero 2.8 GL          |
| ChNo:<br>JMYHNV360YJ001079 | Engine-No:<br>4M40DC9731 | Mileage:<br>118,200 km |



|            |           |           |
|------------|-----------|-----------|
| Scratch: S | Damage: D | Broken: B |
|------------|-----------|-----------|

Remarks:

Technical condition of vehicle:

|                |                                    |
|----------------|------------------------------------|
| Engine: Ok     | Interior: Some stains but unbroken |
| Gearbox: Ok    | Body: See photos above             |
| Brakes: Ok     | Tyres: Good                        |
| Suspension: Ok |                                    |

| Equipments                    |  | To be completed |
|-------------------------------|--|-----------------|
| Radio/ Cassette/ Antenna Yes  |  |                 |
| Car-Keys-spare Yes            |  |                 |
| Multi-lock Yes (Cobra broken) |  |                 |
| Spare Tyre Yes                |  |                 |
| Vehicle Tool kit :Partly      |  |                 |
|                               |  |                 |

Date & Place:HQ,27/02/2008

Signature: