
VEHICLE INSPECTION FORM (to be finalized based on the actual number and type of vehicles)

OSCE 240 MS

N	lumber: OSCE 240 MS	Model/Make: Mitsubishi	Type: Pajero 2.8 GL
	Ch-No:	Engine-No:	Mileage:
	JMYHNV360YJ001049	4M40DC9270	120870 km



Scratch: S	Damage: D	Broken: B	Crack: C

Remarks: Broken rear step; Damage under the front grill guard (bumper)

Technical condition of Vehicle:

Engine:	Average	Interior:	Poor
Gearbox:	Good	Body:	Good
Brakes:	Good	Tyres:	Good
Suspension:	Average		

Spare Tyre-	Set of floor mates-	, ,	Multi-lock-
YES	YES	YES	YES
Radio/ Cassette/ Antenna-	Jack & handle	Fire extinguisher-	Lug wrench tool-
YES	YES	NO	YES
Tool kit- NO	Front grill guard- YES		

Date: 19 Feb. 08	Place: Skopje
Dato. 10 1 00. 00	i idoo. Okopjo