

Annex B

VEHICLE INSPECTION FORM (to be finalized based on the actual number and type of vehicles)

OSCE 510 MS

Number: OSCE 510 MS	Model/Make: Nissan	Type: Teranno II 2.7 TD
Ch-No: VSKTVUR20U0526544	Engine-No: TD27265286Y	Mileage: 58900 km



D

Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Remarks: Engine problem due to accident when vehicle was deep in to the water

Technical condition of Vehicle:

Engine:	Poor	Interior:	Good
Gearbox:	Poor	Body:	Good
Brakes:	Good	Tyres:	Good
Suspension:	Good		

Spare Tyre- YES	Set of floor mates- YES	Car-Keys-spare – YES	Multi-lock- YES
Radio/ Cassette/ Antenna- YES	Jack & handle YES	Fire extinguisher- NO	Lug wrench tool- NO
Tool kit- NO	Front grill guard- NO		

Date: 19 Feb. 08	Place: Skopje
-------------------------	----------------------