

Vehicle Inspection form
-------------------------

063-A-002	VOLVO	S 70
Ch-No: <b>YV1LS7202X2612948</b>	Engine-No: <b>108549</b>	Mileage: <b>189722 km</b>

Asset Number: 30824

Received from Vienna- already used vehicle- in HQ since December 1999

Current location: OSCE Office in Zagreb, Croatia



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Remarks:

Technical condition of vehicle:

Engine: <b>Satisfactorily</b>	Interior: <b>Very Good</b>
Gearbox: <b>Satisfactorily</b>	Body: <b>Small scratches</b>
Brakes: <b>Normal</b>	Tyres: <b>Good</b>
Suspension: <b>Satisfactorily</b>	

Spare Tyre- <b>Normal</b>	Set of floor mates- <b>Yes</b>	Car-Keys-spare – <b>Yes</b>	Multi-lock- <b>Yes</b>
Radio/ Cassette/ Antenna- <b>Yes</b>	Jack & handle <b>Yes</b>	Fire extinguisher- <b>Yes</b>	Lug wrench tool- <b>No</b>
Tool kit- <b>No</b>	Front grill guard- <b>No</b>		

Date & Place: 21.02.2008.	Signature:
---------------------------	------------