

Vehicle Inspection Form

Registration No:	Model	Type
OSCE 487 MS	VW	Golf IV Variant
Chassis Number	Engine Number	Mileage
WVWZZZ1JZ4W109312	AXR 258828	96500 km



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Scratch front left bumper; dent front right door/sleeper
Skopje, 16 March 2010

Registration No:	Model	Type
OSCE 488 MS	VW	Golf IV Variant
Chassis Number	Engine Number	Mileage
WVWZZZ1JZ4W109441	AXR 255967	94700 km



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Vehicle in good condition

Skopje, 18 March 2010

Registration No:	Model	Type
OSCE 489 MS	VW	Golf IV Variant
Chassis Number	Engine Number	Mileage
WVWZZZ1JZ4W109445	AXR 255997	95100 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Front right fender corroded; front protection grill missing; rear bumper small dent

Skopje, 17 March 2010

Registration No:	Model	Type
OSCE 490 MS	VW	Golf IV Variant
Chassis Number	Engine Number	Mileage
WVWZZZ1JZ4W110271	AXR 257327	94000 km



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks:

Skopje, 19 March 2010

Registration No:	Model	Type
OSCE 491 MS	VW	Golf IV Variant
Chassis Number	Engine Number	Mileage
WVWZZZ1JZ4W110434	AXR 258078	98100 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Small dent rear left bumper; small scratch rear right bumper

Skopje, 22 March 2010

Registration No:	Model	Type
OSCE 492 MS	VW	Golf IV Variant
Chassis Number	Engine Number	Mileage
WVWZZZ1JZ4W110894	AXR 258482	96430 km



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Vehicle in very good condition

Skopje, 17 March 2010

Registration No:	Model	Type
OSCE 493 MS	VW	Golf IV Variant
Chassis Number	Engine Number	Mileage
WVWZZZ1JZ4W111494	AXR 259142	94100 km



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Vehicle in good condition

Skopje, 18 March 2010

Registration No:	Model	Type
OSCE 494 MS	VW	Golf IV Variant
Chassis Number	Engine Number	Mileage
WVWZZZ1JZ4W111559	AXR 258518	97400 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Damage rear bumper; rear left fender dented; drivers mirror small crack.

Skopje, 18 March 2010

Registration No:	Model	Type
OSCE 495 MS	VW	Golf IV Variant
Chassis Number	Engine Number	Mileage
WVWZZZ1JZ4W112130	AXR 258525	84600 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Vehicle in good condition

Skopje, 22 March 2010

Registration No:	Model	Type
OSCE 496 MS	VW	Golf IV Variant
Chassis Number	Engine Number	Mileage
WVWZZZ1JZ4W112872	AXR 258952	89130 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks:

Skopje, 17 March 2010

Registration No:	Model	Type
OSCE 516 MS	NISSAN	Teranno II 2.7 TD
Chassis Number	Engine Number	Mileage
VSKTVUR20U0527286	TD27265586Y	78320 km



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks:

Skopje, 17 March 2010

Registration No:	Model	Type
OSCE 517 MS	NISSAN	Teranno II 2.7 TD
Chassis Number	Engine Number	Mileage
VSKTVUR20U0546759	TD27279327Y	75130 km



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks:

Skopje, 18 March 2010

Registration No:	Model	Type
OSCE 518 MS	NISSAN	Teranno II 2.7 TD
Chassis Number	Engine Number	Mileage
VSKTVUR20U0546879	TD27279082Y	75200 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Dent front left bumper

Skopje, 22 March 2010

Registration No:	Model	Type
OSCE 519 MS	NISSAN	Teranno II 2.7 TD
Chassis Number	Engine Number	Mileage
VSKTVUR20U0546940	TD27279521Y	73350 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Front left fender dented

Skopje, 18 March 2010

Registration No:	Model	Type
OSCE 520 MS	NISSAN	Teranno II 2.7 TD
Chassis Number	Engine Number	Mileage
VSKTVUR20U0546978	TD27279079Y	68640 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:
--

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: In good condition

Skopje 22 March 2010

Registration No:	Model	Type
OSCE 521 MS	NISSAN	Teranno II 2.7 TD
Chassis Number	Engine Number	Mileage
VSKTVUR20U0547278	TD27279323Y	67900 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Vehicle in good condition

Skopje

Registration No:	Model	Type
OSCE 522 MS	NISSAN	Teranno II 2.7 TD
Chassis Number	Engine Number	Mileage
VSKTVUR20U0547456	TD27278995Y	71790 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	GOOD
Gear Box:	GOOD	Interior:	GOOD
Brakes:	GOOD	Tires:	GOOD
Suspension:	GOOD	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock/Pin	Jack and handle
YES	YES	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Scratch driver door

Skopje

Registration No:	Model	Type
OSCE 132 MS	Jeep Cherokee	Sport 2.5 TD 4WD
Chassis Number	Engine Number	Mileage
1J4FJ68M6WL128794		41500 km



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Technical condition of Vehicle:

Engine:	AVERAGE	Body exterior:	POOR
Gear Box:	GOOD	Interior:	AVERAGE
Brakes:	GOOD	Tires:	GOOD
Suspension:	AVERAGE	Overall:	AVERAGE

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock	Jack and handle
YES	NO	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	YES	NO	NO

Remarks: Paint affected by all sides

Skopje, 18 March 2010

Registration No:	Model	Type
OSCE 146 MS	Jeep Cherokee	Sport 2.5 TD 4WD
Chassis Number	Engine Number	Mileage
1J4FF68M6XL580988		51110 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	POOR
Gear Box:	GOOD	Interior:	AVERAGE
Brakes:	GOOD	Tires:	GOOD
Suspension:	AVERAGE	Overall:	AVERAGE

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock	Jack and handle
YES	NO	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Winch	Tool box
YES	NO	YES	YES	NO

Remarks: Rear right plastic moulder dented; rear bumper dented; paint affected

Skopje, 16 March 2010

Registration No:	Model	Type
OSCE 346 MS	SCANIA	Century Scania Bus / Coach
Chassis Number	Engine Number	Mileage
YS4K4X20001839469	6133647	245100 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Technical condition of Vehicle:

Engine:	GOOD	Body exterior:	POOR
Gear Box:	GOOD	Interior:	AVERAGE
Brakes:	GOOD	Tires:	GOOD
Suspension:	AVERAGE	Overall:	GOOD

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock	Jack and handle
YES	NO	YES	YES	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	YES	NO	NO

Remarks:

Skopje, 17 March 2010

Registration No:	Model	Type
OSCE 347 MS	DAF	Daf TRUCK 1800
Chassis Number	Engine Number	Mileage
218618	E-64368	55600 km



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Technical condition of Vehicle:

Engine:	AVERAGE	Body exterior:	POOR
Gear Box:	GOOD	Interior:	POOR
Brakes:	GOOD	Tires:	GOOD
Suspension:	AVERAGE	Overall:	AVERAGE

Vehicle equipment:

Spare Tire	Radio / CD player	Floor mates	Multi lock	Jack and handle
YES	NO	YES	NO	YES
Spare keys	Fire extinguisher	Front grill guard	Tool kit	Tool box
YES	NO	NO	NO	NO

Remarks: Damage rear upper side of tail lift

Skopje, 16 March 2010