

**VEHICLE INSPECTION FORM**  
(to be finalized based on the actual number and type of vehicles)

<b>Number:</b> OSCE 010 MY	<b>Model/Make:</b> MITSUBISHI	<b>Type:</b> PAJERO
<b>Ch-No:</b> JMYHNV360YJ001057	<b>Engine-No:</b> 4M40 DC 9391	<b>Mileage:</b> 117500 km



<b>Scratch:</b> S	<b>Damage:</b> D	<b>Broken:</b> B	<b>Crack:</b> C
-------------------	------------------	------------------	-----------------

Remarks:

Technical condition of Vehicle:

Engine:	Good	Interior:	OK
Gearbox:	Good	Body:	OK
Brakes:	Good	Tyres:	Good
Suspension:	Good		

Spare Tyre- YES	Set of floor mates- YES	Car-Keys-spare – YES	Multi-lock- YES
Radio/ Cassette/ Antenna-YES	Jack & handle YES	Fire extinguisher- NO	Lug wrench tool- YES
Tool kit- YES	Front grill guard- YES		

<b>Date:</b> 26.02.2008	<b>Place:</b> Belgrade
-------------------------	------------------------