

Annex B

VEHICLE INSPECTION FORM (to be finalized based on the actual number and type of vehicles)

OSCE 244 MS

Number: OSCE 244MS	Model/Make: Mitsubishi	Type: Pajero 2.8 GL
Ch-No: JMYHNV360YJ001059	Engine-No: 4M40DC9237	Mileage: 101750 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Remarks: NIL

Technical condition of Vehicle:

Engine:	Average	Interior:	Poor
Gearbox:	Good	Body:	Good
Brakes:	Good	Tyres:	Good
Suspension:	Good		

Spare Tyre- YES	Set of floor mates- YES	Car-Keys-spare – YES	Multi-lock- YES
Radio/ Cassette/ Antenna- YES	Jack & handle YES	Fire extinguisher- NO	Lug wrench tool- YES
Tool kit- NO	Front grill guard- YES		

Date: 19 Feb. 08 Place: Skopje