

## Annex B

### VEHICLE INSPECTION FORM (to be finalized based on the actual number and type of vehicles)

#### OSCE 307 MS

<b>Number: OSCE 307 MS</b>	<b>Model/Make: VW</b>	<b>Type: Minibus Transporter</b>
<b>Ch-No:</b> WV2ZZZ70Z2H017757	<b>Engine-No:</b>	<b>Mileage:</b> 88.000 km



S

<b>Scratch: S</b>	<b>Damage: D</b>	<b>Broken: B</b>	<b>Crack: C</b>
-------------------	------------------	------------------	-----------------

**Remarks:** Front right bumper holder broken

#### Technical condition of Vehicle:

<b>Engine:</b>	Good	<b>Interior:</b>	Good
<b>Gearbox:</b>	Good	<b>Body:</b>	Good
<b>Brakes:</b>	Good	<b>Tyres:</b>	Good
<b>Suspension:</b>	Good		

Spare Tyre- YES	Set of floor mates- YES	Car-Keys-spare – YES	Multi-lock- NO
Radio/ Cassette/ Antenna- YES	Jack & handle YES	Fire extinguisher- NO	Lug wrench tool- NO
Tool kit- NO	Front grill guard- NO		

<b>Date: 19 Feb. 08</b>	<b>Place: Skopje</b>
-------------------------	----------------------