

## Vehicle Inspection form

OSCE – Plate	Type	Model
OSCE 041 PA	Mitsubishi	Pajero 2.8 GL
ChNo: JMYHNV360YJ001081	Engine-No: 4M40DC9019	Mileage: 133,215 km



Scratch: S	Damage: D	Broken: B
------------	-----------	-----------

Remarks:

Technical condition of vehicle:

Engine: Ok	Interior: Some stain but unbroken
Gearbox: Ok	Body: see pictures above
Brakes: Ok	Tyres: 50% consumed
Suspension: Ok	

Equipments		To be completed
Radio/ Cassette/ Antenna Yes		
Car-Keys-spare Yes		
Multi-lock Yes Cobra broken		
Spare Tyre Yes		
Vehicle Tool kit Yes		

Date & Place: 27/02/2008, Tirana	Signature:
----------------------------------	------------