

Annex B

VEHICLE INSPECTION FORM (to be finalized based on the actual number and type of vehicles)

OSCE 509 MS

Number: OSCE 509 MS	Model/Make: Nissan	Type: Teranno II 2.7 TD
Ch-No: VSKTVUR20U0510707	Engine-No: TD27257412Y	Mileage: 47600 km



Scratch: S	Damage: D	Broken: B	Crack: C
-------------------	------------------	------------------	-----------------

Remarks: NIL

Technical condition of Vehicle:

Engine:	Good	Interior:	Good
Gearbox:	Poor	Body:	Good
Brakes:	Good	Tyres:	Good
Suspension:	Poor		

Spare Tyre- YES	Set of floor mates- YES	Car-Keys-spare – YES	Multi-lock- YES
Radio/ Cassette/ Antenna- YES	Jack & handle YES	Fire extinguisher- NO	Lug wrench tool- NO
Tool kit- NO	Front grill guard- NO		

Date: 20 Feb. 08 Place: Skopje