

Vehicle Inspection form

OSCE-011-MM	Mitsubishi	Pajero
Ch-No: JMYHNV360YJ001070	Engine-No: 4M40DC9675	Mileage: 175,500



Scratch: S	Damage: D	Broken: B	Crack: C
------------	-----------	-----------	----------

Remarks:

Technical condition of vehicle:

Engine: Good	Interior: Good
Gearbox: Good	Body: Small scratches/
Brakes: Normal	Tyres: Good
Suspension: Satisfactorily	

Spare Tyre- Good	Set of floor mates- Yes	Car-Keys-spare – Yes	Multi-lock- Yes
Radio/ Cassette/ Antenna- Yes	Jack & handle Yes	Fire extinguisher- Yes	Lug wrench tool- No
Tool kit- Yes	Front grill guard- Yes	Triangle- Yes	

Date & Place: 11.03.2008.	Signature:
---------------------------	------------