

VEHICLE INSPECTION FORM
(to be finalized based on the actual number and type of vehicles)

| | | |
|------------------------------------|------------------------------------|--------------------------|
| Number: OSCE 018 MY | Model/Make: MITSHUBISHI | Type: L-300 |
| Ch-No: JMYHNP15WYA000800 | Engine-No: 4D 56 JT 2598 | Mileage: 61100 |



| | | | |
|-------------------|------------------|------------------|-----------------|
| Scratch: S | Damage: D | Broken: B | Crack: C |
|-------------------|------------------|------------------|-----------------|

Remarks:

Technical condition of Vehicle:

| | |
|------------------|----------------|
| Engine: Good | Interior: Good |
| Gearbox: Good | Body: Good |
| Brakes: Good | Tyres: Good |
| Suspension: Good | |

| | | | |
|-------------------------------|------------------------|------------------------|----------------------|
| Spare Tyre- YES | Set of floor mates- NO | Car-Keys-spare – YES | Multi-lock- YES |
| Radio/ Cassette/ Antenna- YES | Jack & handle YES | Fire extinguisher- YES | Lug wrench tool- YES |
| Tool kit- YES | Front grill guard- NO | | |

| | |
|-------------------------|------------------------|
| Date: 26.02.2008 | Place: BELGRADE |
|-------------------------|------------------------|